



PROJECT PROFILE

PROJECT: Lining Of A Swimming Pool

LOCATION: Israel

THE PROBLEM

This swimming pool was at the residence of the Turkish Ambassador for Israel. The swimming pool had been allowed to deteriorate badly and all internal surfaces were now in need of complete refurbishment.

The basic structure of the pool was sound, therefore a coating system that would provide good waterproofing and protection was required. The selected coating system needed to offer protection to both the floors and the side walls.



THE SOLUTION



The swimming pool was first of all cleaned to ensure any contamination was removed from all surfaces. The pool was then allowed to dry out completely before being overcoated with one coat of Uni-Tech GP Primer and two coats of Uni-Tech UV in blue.

As is evident from the photograph, this coating system has provided an excellent finish, transforming the appearance of this swimming pool.